

FIELD OFFICE TECHNICAL GUIDE Sec. II  
WASTE DISPOSAL INTERPRETATIONS

Sanitary Facilities - Part 1.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Monroe County, Iowa

Map symbol and soil name	Pct. of map unit	Septic tank absorption fields		Sewage lagoons	
		Rating class and limiting features	Value	Rating class and limiting features	Value
11B: Colo-----	55	Very limited Flooding Depth to saturated zone restricted permeability	1.00 1.00 0.25	Very limited Flooding Depth to saturated zone Seepage	1.00 1.00 0.50
Ely-----	30	Very limited Depth to saturated zone restricted permeability	1.00 0.25	Very limited Depth to saturated zone Seepage Slope	1.00 0.50 0.33
13B: Olmitz-----	40	Somewhat limited Depth to saturated zone restricted permeability	0.43 0.25	Somewhat limited Seepage Slope	0.50 0.33
Colo-----	30	Very limited Flooding Depth to saturated zone restricted permeability	1.00 1.00 0.25	Very limited Flooding Depth to saturated zone Seepage	1.00 1.00 0.50
Vesser-----	20	Very limited Flooding Depth to saturated zone restricted permeability	1.00 1.00 0.25	Very limited Flooding Depth to saturated zone Seepage	1.00 1.00 0.50
23C: Arispe-----	95	Very limited Depth to saturated zone Restricted permeability	1.00 0.99	Very limited Depth to saturated zone Slope Seepage	1.00 1.00 0.50

FIELD OFFICE TECHNICAL GUIDE Sec. II  
WASTE DISPOSAL INTERPRETATIONS

Sanitary Facilities - Part 1.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Monroe County, Iowa

Map symbol and soil name	Pct. of map unit	Septic tank absorption fields		Sewage lagoons	
		Rating class and limiting features	Value	Rating class and limiting features	Value
23C2: Arispe-----	95	Very limited Depth to saturated zone Restricted permeability	1.00  0.99	Very limited Depth to saturated zone Slope  Seepage	1.00  1.00  0.50
24D2: Shelby-----	90	Somewhat limited Restricted permeability Slope	0.91  0.63	Very limited Slope	1.00
24E2: Shelby-----	90	Very limited Slope Restricted permeability	1.00 0.91	Very limited Slope	1.00
41D: Sparta-----	100	Very limited Filtering capacity Slope	1.00  0.16	Very limited Seepage  Slope	1.00  1.00
51: Vesser-----	95	Very limited Flooding Depth to saturated zone restricted permeability	1.00 1.00  0.25	Very limited Flooding Depth to saturated zone Seepage	1.00 1.00  0.50
54: Zook-----	95	Very limited Flooding Depth to saturated zone Restricted permeability	1.00 1.00  0.99	Very limited Flooding Depth to saturated zone	1.00 1.00

FIELD OFFICE TECHNICAL GUIDE Sec. II  
WASTE DISPOSAL INTERPRETATIONS

Sanitary Facilities - Part 1.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Monroe County, Iowa

Map symbol and soil name	Pct. of map unit	Septic tank absorption fields		Sewage lagoons	
		Rating class and limiting features	Value	Rating class and limiting features	Value
54+: Zook-----	95	Very limited Flooding Depth to saturated zone Restricted permeability	 1.00 1.00  0.99	Very limited Flooding Depth to saturated zone	 1.00 1.00
58D2: Douds-----	95	Somewhat limited Slope Depth to saturated zone restricted permeability	 0.63 0.40 0.35	Very limited Slope Seepage	 1.00 1.00
58E2: Douds-----	95	Very limited Slope Depth to saturated zone restricted permeability	 1.00 0.40 0.35	Very limited Slope Seepage	 1.00 1.00
65D: Lindley-----	100	Very limited Restricted permeability Slope	 1.00  0.63	Very limited Slope	 1.00
65E: Lindley-----	95	Very limited Slope Restricted permeability	 1.00 1.00	Very limited Slope	 1.00
65E2: Lindley-----	95	Very limited Slope Restricted permeability	 1.00 1.00	Very limited Slope	 1.00

FIELD OFFICE TECHNICAL GUIDE Sec. II  
WASTE DISPOSAL INTERPRETATIONS

Sanitary Facilities - Part 1.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Monroe County, Iowa

Map symbol and soil name	Pct. of map unit	Septic tank absorption fields		Sewage lagoons	
		Rating class and limiting features	Value	Rating class and limiting features	Value
65G: Lindley-----	95	Very limited Slope Restricted permeability	1.00 1.00	Very limited Slope	1.00
76B: Ladoga-----	95	Very limited Restricted permeability Depth to saturated zone	1.00 0.40	Somewhat limited Seepage Slope	0.50 0.33
76C: Ladoga-----	100	Very limited Restricted permeability Depth to saturated zone	1.00 0.40	Very limited Slope Seepage	1.00 0.50
76C2: Ladoga-----	100	Very limited Restricted permeability Depth to saturated zone	1.00 0.40	Very limited Slope Seepage	1.00 0.50
76D: Ladoga-----	95	Very limited Restricted permeability Slope Depth to saturated zone	1.00 0.63 0.40	Very limited Slope Seepage	1.00 0.50
76D2: Ladoga-----	100	Very limited Restricted permeability Slope Depth to saturated zone	1.00 0.63 0.40	Very limited Slope Seepage	1.00 0.50

FIELD OFFICE TECHNICAL GUIDE Sec. II  
WASTE DISPOSAL INTERPRETATIONS

Sanitary Facilities - Part 1.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Monroe County, Iowa

Map symbol and soil name	Pct. of map unit	Septic tank absorption fields		Sewage lagoons	
		Rating class and limiting features	Value	Rating class and limiting features	Value
80D: Clinton-----	95	Very limited Restricted permeability Slope Depth to saturated zone	1.00 0.63 0.40	Very limited Slope Seepage	1.00 0.50
80D2: Clinton-----	100	Very limited Restricted permeability Slope Depth to saturated zone	1.00 0.63 0.40	Very limited Slope Seepage	1.00 0.50
130: Belinda-----	95	Very limited Restricted permeability Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 0.50
131B: Pershing-----	95	Very limited Restricted permeability Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Slope	1.00 0.33
131C: Pershing-----	90	Very limited Restricted permeability Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Slope	1.00 1.00
132B: Weller-----	95	Very limited Restricted permeability Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Slope	1.00 0.33

FIELD OFFICE TECHNICAL GUIDE Sec. II  
WASTE DISPOSAL INTERPRETATIONS

Sanitary Facilities - Part 1.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Monroe County, Iowa

Map symbol and soil name	Pct. of map unit	Septic tank absorption fields		Sewage lagoons	
		Rating class and limiting features	Value	Rating class and limiting features	Value
132C: Weller-----	100	Very limited Restricted permeability Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Slope	1.00 1.00
133: Colo-----	100	Very limited Flooding Depth to saturated zone restricted permeability	1.00 1.00 0.25	Very limited Flooding Depth to saturated zone Seepage	1.00 1.00 0.50
133+: Colo-----	100	Very limited Flooding Depth to saturated zone restricted permeability	1.00 1.00 0.25	Very limited Flooding Depth to saturated zone Seepage	1.00 1.00 0.50
133B: Colo-----	100	Very limited Depth to saturated zone restricted permeability	1.00 0.25	Very limited Depth to saturated zone Seepage Slope	1.00 1.00 0.50 0.33
179D2: Gara-----	90	Very limited Restricted permeability Slope	1.00 0.63	Very limited Slope	1.00
179E2: Gara-----	100	Very limited Slope Restricted permeability	1.00 1.00	Very limited Slope	1.00

FIELD OFFICE TECHNICAL GUIDE Sec. II  
WASTE DISPOSAL INTERPRETATIONS

Sanitary Facilities - Part 1.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Monroe County, Iowa

Map symbol and soil name	Pct. of map unit	Septic tank absorption fields		Sewage lagoons	
		Rating class and limiting features	Value	Rating class and limiting features	Value
179F: Gara-----	90	Very limited Slope Restricted permeability	1.00 1.00	Very limited Slope	1.00
179F2: Gara-----	90	Very limited Slope Restricted permeability	1.00 1.00	Very limited Slope	1.00
192D2: Adair-----	90	Very limited Depth to saturated zone Restricted permeability Slope	1.00 0.99 0.63	Very limited Slope Depth to saturated zone	1.00 1.00
211: Edina-----	95	Very limited Depth to saturated zone Restricted permeability	1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 0.50
220: Nodaway-----	95	Very limited Flooding Depth to saturated zone restricted permeability	1.00 1.00 0.25	Very limited Flooding Depth to saturated zone Seepage	1.00 0.71 0.50
222C: Clarinda-----	90	Very limited Depth to saturated zone Restricted permeability	1.00 1.00	Very limited Depth to saturated zone Slope	1.00 1.00

FIELD OFFICE TECHNICAL GUIDE Sec. II  
WASTE DISPOSAL INTERPRETATIONS

Sanitary Facilities - Part 1.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Monroe County, Iowa

Map symbol and soil name	Pct. of map unit	Septic tank absorption fields		Sewage lagoons	
		Rating class and limiting features	Value	Rating class and limiting features	Value
222C2: Clarinda-----	90	Very limited Depth to saturated zone Restricted permeability	1.00 1.00	Very limited Depth to saturated zone Slope	1.00 1.00
222D2: Clarinda-----	90	Very limited Depth to saturated zone Restricted permeability Slope	1.00 1.00 0.63	Very limited Slope Depth to saturated zone	1.00 1.00
223C2: Rinda-----	95	Very limited Restricted permeability Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Slope	1.00 1.00
223D2: Rinda-----	95	Very limited Restricted permeability Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Slope Depth to saturated zone	1.00 1.00
260: Beckwith-----	95	Very limited Restricted permeability Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 0.50
263: Okaw-----	95	Very limited Restricted permeability Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone	1.00



FIELD OFFICE TECHNICAL GUIDE Sec. II  
WASTE DISPOSAL INTERPRETATIONS

Sanitary Facilities - Part 1.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Monroe County, Iowa

Map symbol and soil name	Pct. of map unit	Septic tank absorption fields		Sewage lagoons	
		Rating class and limiting features	Value	Rating class and limiting features	Value
273C: Olmitz-----	100	Somewhat limited Depth to saturated zone restricted permeability	0.43 0.25	Very limited Slope Seepage	1.00 0.50
279: Taintor-----	90	Very limited Depth to saturated zone Restricted permeability	1.00 0.91	Very limited Depth to saturated zone Seepage	1.00 0.50
280: Mahaska-----	90	Very limited Depth to saturated zone restricted permeability	1.00 0.25	Very limited Depth to saturated zone Seepage	1.00 0.50
281B: Otley-----	95	Somewhat limited Depth to saturated zone restricted permeability	0.40 0.25	Somewhat limited Seepage Slope	0.50 0.33
281C: Otley-----	95	Somewhat limited Depth to saturated zone restricted permeability	0.40 0.25	Very limited Slope Seepage	1.00 0.50
281C2: Otley-----	100	Somewhat limited Depth to saturated zone restricted permeability	0.40 0.25	Very limited Slope Seepage	1.00 0.50

FIELD OFFICE TECHNICAL GUIDE Sec. II  
WASTE DISPOSAL INTERPRETATIONS

Sanitary Facilities - Part 1.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Monroe County, Iowa

Map symbol and soil name	Pct. of map unit	Septic tank absorption fields		Sewage lagoons	
		Rating class and limiting features	Value	Rating class and limiting features	Value
313D: Gosport-----	95	Very limited Depth to bedrock	1.00	Very limited Depth to soft bedrock	1.00
		Depth to saturated zone	1.00	Slope	1.00
		Restricted permeability	1.00	Depth to saturated zone	1.00
		Slope	0.63		
313D2: Gosport-----	95	Very limited Depth to bedrock	1.00	Very limited Depth to soft bedrock	1.00
		Depth to saturated zone	1.00	Slope	1.00
		Restricted permeability	1.00	Depth to saturated zone	1.00
		Slope	0.63		
313E: Gosport-----	85	Very limited Depth to bedrock	1.00	Very limited Depth to soft bedrock	1.00
		Depth to saturated zone	1.00	Slope	1.00
		Restricted permeability	1.00	Depth to saturated zone	1.00
		Slope	1.00		
313E2: Gosport-----	85	Very limited Depth to bedrock	1.00	Very limited Depth to soft bedrock	1.00
		Depth to saturated zone	1.00	Slope	1.00
		Restricted permeability	1.00	Depth to saturated zone	1.00
		Slope	1.00		

FIELD OFFICE TECHNICAL GUIDE Sec. II  
WASTE DISPOSAL INTERPRETATIONS

Sanitary Facilities - Part 1.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Monroe County, Iowa

Map symbol and soil name	Pct. of map unit	Septic tank absorption fields		Sewage lagoons	
		Rating class and limiting features	Value	Rating class and limiting features	Value
313F: Gosport-----	85	Very limited Depth to bedrock	1.00	Very limited Depth to soft bedrock	1.00
		Depth to saturated zone	1.00	Slope	1.00
		Slope	1.00	Depth to saturated zone	1.00
		Restricted permeability	1.00		
362: Haig-----	90	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
		Restricted permeability	0.99	Seepage	0.50
364B: Grundy-----	100	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
		Restricted permeability	0.99	Slope	0.33
419D2: Vanmeter-----	100	Very limited Depth to bedrock	1.00	Very limited Depth to soft bedrock	1.00
		Depth to saturated zone	1.00	Slope	1.00
		Restricted permeability	1.00	Depth to saturated zone	1.00
		Slope	0.63		
419E2: Vanmeter-----	100	Very limited Depth to bedrock	1.00	Very limited Depth to soft bedrock	1.00
		Depth to saturated zone	1.00	Slope	1.00
		Restricted permeability	1.00	Depth to saturated zone	1.00
		Slope	1.00		

FIELD OFFICE TECHNICAL GUIDE Sec. II  
WASTE DISPOSAL INTERPRETATIONS

Sanitary Facilities - Part 1.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Monroe County, Iowa

Map symbol and soil name	Pct. of map unit	Septic tank absorption fields		Sewage lagoons	
		Rating class and limiting features	Value	Rating class and limiting features	Value
423D2: Bucknell-----	95	Very limited Restricted permeability Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Slope Depth to saturated zone	1.00 1.00
424E2: Lindley-----	60	Very limited Slope Restricted permeability	1.00 1.00	Very limited Slope	1.00
Keswick-----	30	Very limited Restricted permeability Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Slope Depth to saturated zone	1.00 1.00
425C: Keswick-----	95	Very limited Restricted permeability Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Slope	1.00 1.00
425D: Keswick-----	95	Very limited Restricted permeability Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Slope Depth to saturated zone	1.00 1.00
425D2: Keswick-----	100	Very limited Restricted permeability Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Slope Depth to saturated zone	1.00 1.00

FIELD OFFICE TECHNICAL GUIDE Sec. II  
WASTE DISPOSAL INTERPRETATIONS

Sanitary Facilities - Part 1.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Monroe County, Iowa

Map symbol and soil name	Pct. of map unit	Septic tank absorption fields		Sewage lagoons	
		Rating class and limiting features	Value	Rating class and limiting features	Value
428B: Ely-----	95	Very limited Depth to saturated zone restricted permeability	1.00  0.25	Very limited Depth to saturated zone Seepage  Slope	1.00  0.50  0.33
452C: Lineville-----	100	Very limited Restricted permeability Depth to saturated zone	1.00  1.00	Very limited Depth to saturated zone Slope	1.00  1.00
478G: Gosport-----	60	Very limited Depth to bedrock  Depth to saturated zone Restricted permeability Slope	1.00  1.00 1.00 1.00 1.00	Very limited Depth to soft bedrock Slope  Depth to saturated zone	1.00  1.00  1.00
Rock Outcrop-----	30	Not rated		Not rated	
484: Lawson-----	95	Very limited Flooding Depth to saturated zone restricted permeability	1.00 1.00 0.25	Very limited Flooding Depth to saturated zone Seepage	1.00 1.00 0.50
594C2: Galland-----	95	Very limited Restricted permeability Depth to saturated zone	1.00 1.00	Very limited Seepage Slope  Depth to saturated zone	1.00  1.00  0.71

FIELD OFFICE TECHNICAL GUIDE Sec. II  
WASTE DISPOSAL INTERPRETATIONS

Sanitary Facilities - Part 1.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Monroe County, Iowa

Map symbol and soil name	Pct. of map unit	Septic tank absorption fields		Sewage lagoons	
		Rating class and limiting features	Value	Rating class and limiting features	Value
594D2: Galland-----	95	Very limited Restricted permeability Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Slope Seepage Depth to saturated zone	1.00 1.00 0.71
688: Koszta-----	95	Very limited Depth to saturated zone restricted permeability	1.00 0.35	Very limited Depth to saturated zone Seepage	1.00 0.50
731C2: Pershing-----	90	Very limited Restricted permeability Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Slope	1.00 1.00
731D2: Pershing-----	90	Very limited Restricted permeability Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Slope Depth to saturated zone	1.00 1.00
732C2: Weller-----	90	Very limited Restricted permeability Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Slope	1.00 1.00
732D2: Weller-----	90	Very limited Restricted permeability Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Slope Depth to saturated zone	1.00 1.00

FIELD OFFICE TECHNICAL GUIDE Sec. II  
WASTE DISPOSAL INTERPRETATIONS

Sanitary Facilities - Part 1.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Monroe County, Iowa

Map symbol and soil name	Pct. of map unit	Septic tank absorption fields		Sewage lagoons	
		Rating class and limiting features	Value	Rating class and limiting features	Value
792C2: Armstrong-----	95	Very limited Restricted permeability Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Slope	1.00 1.00
792D2: Armstrong-----	95	Very limited Restricted permeability Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Slope Depth to saturated zone	1.00 1.00
795D: Ashgrove-----	100	Very limited Restricted permeability Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Slope Depth to saturated zone	1.00 1.00
822D2: Lamoni-----	100	Very limited Depth to saturated zone Restricted permeability Slope	1.00 0.99 0.63	Very limited Slope Depth to saturated zone	1.00 1.00
832C2: Weller-----	90	Very limited Restricted permeability Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Slope	1.00 1.00
876B: Ladoga-----	100	Very limited Restricted permeability Depth to saturated zone	1.00 0.40	Somewhat limited Seepage Slope	0.50 0.33

FIELD OFFICE TECHNICAL GUIDE Sec. II  
WASTE DISPOSAL INTERPRETATIONS

Sanitary Facilities - Part 1.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Monroe County, Iowa

Map symbol and soil name	Pct. of map unit	Septic tank absorption fields		Sewage lagoons	
		Rating class and limiting features	Value	Rating class and limiting features	Value
876C2: Ladoga-----	95	Very limited Restricted permeability Depth to saturated zone	1.00 0.40	Very limited Slope Seepage	1.00 0.50
993D2: Gara-----	60	Very limited Restricted permeability Slope	1.00 0.63	Very limited Slope	1.00
Armstrong-----	30	Very limited Restricted permeability Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Slope Depth to saturated zone	1.00 1.00
993E2: Gara-----	60	Very limited Slope Restricted permeability Depth to saturated zone	1.00 1.00 0.43	Very limited Slope	1.00
Armstrong-----	30	Very limited Restricted permeability Depth to saturated zone Slope	1.00 1.00 0.63	Very limited Slope Depth to saturated zone	1.00 1.00
1130: Belinda-----	100	Very limited Restricted permeability Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 0.50



FIELD OFFICE TECHNICAL GUIDE Sec. II  
WASTE DISPOSAL INTERPRETATIONS

Sanitary Facilities - Part 1.

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Monroe County, Iowa

Map symbol and soil name	Pct. of map unit	Septic tank absorption fields		Sewage lagoons	
		Rating class and limiting features	Value	Rating class and limiting features	Value
1131C: Pershing-----	100	Very limited Restricted permeability Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Slope	1.00 1.00
1279: Taintor-----	100	Very limited Depth to saturated zone Restricted permeability	1.00 0.91	Very limited Depth to saturated zone Seepage	1.00 0.50
5020: Dumps-----	50	Not rated		Not rated	
Pits-----	50	Not rated		Not rated	
5021: Orthents-----	100	Not rated		Not rated	
5030: Pits-----	100	Not rated		Not rated	
5040: Orthents-----	100	Not rated		Not rated	
W: Water-----	100	Not rated		Not rated	